Admission date	Realization date	Signature	Remarks

Zakład elektroniczny TATAREK Jerzy Tatarek
50-559 Wroclaw, 75 Swieradowska st.
ph. (071) 367-21-67, 373-14-88, fax 373-14-58; Tax index number 899-020-21-48;
Bank account: BZ WBK S.A. WROCLAW 6910901522-0000-0000-5201-9335
www.tatarek.com.pl.; E-mail: tatarek@tatarek.com.pl

Zakład elektroniczny TATAREK Jerzy Tatarek

USER MANUAL

INTEGRATOR of PUMPS 2/1


1. Basic parameters of the integrator

Power	230V AC/50Hz
Maximum connection power	1500W
Operation conditions	0÷50°C, humidity 10÷90% without condensation
Coil of the relay P1	230V AC
Coil of the relay P2	230V AC


2. Principle of operation

The integrator of pumps 2/1 is applicable to the heating system with the C.H. pumps, water jacket stove and C.H. furnace. It integrates the operation of 2 pumps into one C.H. pump operation

3.Connection diagram of the integrator



4. Schematic diagram



WARRANTY

1.Warranty is valid [24] months from the date of sale of the integrator
2.Producer does not take responsibility for any mechanical damages made by user.
3.MAKING REPAIRS OR MODYFYING THE INTEGRATOR BY USER IS FORBIDDEN AND CAUSES WARRANTY CANCELATION
4.Warranty card is valid only with date of sale, seller's signature and stamp
5.Warranty and after-warranty repairs should be done only by producer, damaged integrators should be sent to the producer in order to make all repairs needed.
6.Warranty protection involves the EU
7.Warranty does not exclude, not restrict and not suspend buyer's rights coming from the incompatibility of the article with the agreement (Laws Journal No. 141 Pos. 1176)

WARNING !

ANY MODIFICATION OF THE INTEGRATOR MADE BY THE USER CAN BE THE CAUSE OF SAFETY CONDITIONS DETERIORATION AND CAN EXPOSE THE USER TO ELECTRIC SHOCK OR DAMAGE DEVICES SUPPLIED.

Connection cable of the integrator may be replaced only by the producer or his authorized service

WARNING!
1. Producer does not take the responsibility for damage caused by atmospheric discharge
2. and overvoltage in the mains
3. Burnt fuses are not subject to warranty replacement

Date of sale **Seller's signature and stamp**

Register No.. GIOS: E 0002240WZ

Worn out electronic and electric devices must be transfered to the utilization collection place, where will be accepted for free

ARGO-FILM
Recycling Plant No. 6
180 Krakowska st., 52-015 Wroclaw
ph.: 071 794 43 01,
0 515 122 142

Zakład elektroniczny TATAREK Jerzy Tatarek

50-559 Wroclaw, 75 Swieradowska st
ph. (071) 367-21-67, 373-14-88, fax 373-14-58; tax index number 899-020-21-48;
Bank account : BZ WBK S.A. O/WROCŁAW 69109015220000000052019335
www.tatarek.com.pl.; E-mail: tatarek@tatarek.com.pl